

DC VOLTAGE MEASUREMENT

1. Connect red test lead to "V Ω mA" jack, Black lead to "COM" jack.
2. Set RANGE switch to desired DCV position, if the voltage to be measured is not known beforehand, set switch to the highest range and reduce it until satisfactory reading is obtained.
3. Connect test leads to device or circuit being measured.
4. Turn on power of the device or circuit being measured voltage value will appear on Digital Display along with the voltage polarity.

AC VOLTAGE MEASUREMENT

1. Red lead to "V Ω mA". Black lead to "COM" (for measurements between 200mA and 10A connect red lead to "10A" jack with fully depressed.)
2. RANGE switch to desired DCA position.
3. Open the circuit to be measured, and connect test leads IN SERIES with the load in which current is to be measured.
4. Read current value on Digital Display.

RESISTANCE MEASUREMENT

1. Red lead to "V Ω mA". Black lead to "COM".
2. RANGE switch to desired OHM position.

3. If the resistance being measured is connected to a circuit, turn off power and discharge all capacitors before measurement.
4. Connect test leads to circuit being measured.
5. Read resistance value on Digital Display.

DIODE MEASUREMENT

1. Red lead to "V Ω mA", Black lead to "COM".
2. RANGE switch to " \rightarrow " position.
3. Connect the red test lead to the anode of the diode to be measured and black test lead to cathode.
4. The forward voltage drop in mV will be displayed. If the diode is reversed, figure "1" will be shown.

TRANSISTOR hFE MEASUREMENT

1. RANGE switch to the hFE position.
2. Determine whether the transistor is PNP or NPN type and locate the Emitter, Base and Collector leads. Insert the leads into the proper holes of the hFE Socket on the front panel.
3. The meter will display the approximate hFE value at the condition of base current 10 μ A and V_{CE} 2.8V.

TEMPERATURE MEASUREMENT

1. Connect the K type thermoelectric couple to

- "V Ω mA" and "COM" jacks.
- RANGE switch to TEMP position.
- The display will read Temperature value °C.

AUDIBLE CONTINUITY TEST

1. Red lead to "V Ω mA", Black lead to "COM".
2. RANGE switch to " ∞ " position.
3. Connect test leads to two points of circuit to be tested. If the resistance is lower than 30 Ω \pm 20 Ω , the buzzer will sound.

TEST SIGNAL USE

1. RANGE switch to " \square " position.
2. A test signal (50Hz) appears between "V Ω mA" and "COM" jack, the output voltage is approx 5V p-p with 50K Ω impedance.

BATTERY AND FUSE REPLACEMENT

Fuse rarely need replacement and blow almost always as a result of operator error. If " ∞ " appears in display, it indicates that the battery should be replaced. To replace battery & Fuse (200mA/250V) remove the 2 screws in the bottom of the case, simply remove the old, and replace with a new one. Be careful to observe polarity.

CAUTION

Before attempting to open the case of the instrument, be sure to disconnect test leads from any energized circuits to avoid shock hazard.

ACCESSORIES

- Operator's instruction manual
- Set of test leads
- Gift box
- K type thermoelectric couple (830C.837,838 only)
- 9-volt battery, NEDA 1604 6F22 type.

OPERATOR'S INSTRUCTION MANUAL

83 SERIES

DIGITAL MULTIMETER

WARNING

READ AND UNDERSTAND THIS MANUAL


BEFORE USING THE INSTRUMENT

Failure to understand and comply with the

WARNINGS and operating instructions can

result in serious or fatal injuries and/or

property damage.



General

These 83 series instruments are a series of compact pocket-sized 3 1/2 digit multimeters for measuring DC and AC Voltage, DC Current, Resistance and Diode. Some of those also provide Temperature, Transistor measurement and audible continuity test function or can be used as a signal generator(see table). Full range overload protection and low battery voltage indication are provided. They are ideal instruments for use in fields, such as laboratory, workshop, DIYers and home applications.

M83 Series Multimeters

Model	DCV	ACV	DCA	OHM	hFE	BAT	Ω	T	RT
830A	✓	✓	✓	✓	✓	✓			
830B	✓	✓	✓	✓	✓	✓			
830C	✓	✓	✓	✓	✓	✓		✓	
830D	✓	✓	✓	✓	✓	✓	✓		
831	✓	✓	✓	✓	✓				
832	✓	✓	✓	✓	✓	✓	✓	✓	
833	✓	✓	✓	✓	✓	✓	✓	✓	
835	✓	✓	✓	✓	✓	✓	✓	✓	✓
837	✓	✓	✓	✓	✓	✓	✓	✓	✓
838	✓	✓	✓	✓	✓	✓	✓	✓	✓

*RT: Room Temperature

FRONT PANEL DESCRIPTION

- FUNCTION AND RANGE SWITCH**
This switch is used to select the function and desired range as well as to turn on the

instrument.

To extend the life of this battery, the switch should be in the "OFF" position when the instrument is not in use.

- DISPLAY**
3 1/2 digit, 7 segment, 0.5" high LCD.
- "Common" JACK**
Plug in connector for black (negative) test lead.
- "VΩ mACx" JACK**
Plug in connector for red (Positive) test lead for all voltage and resistance and current (except 10A) measurements.
- "10A" JACK**
Plug in connector to red (positive) test lead for 10A measurement.

SPECIFICATIONS

Accuracies are guaranteed for 1 year, 23°C ± 5, less than 80%RH

DC VOLTAGE

RANGE	RESOLUTION	ACCURACY
200mV	100μV	±0.5% of rdg ± 2D
2000mV	1mV	±0.5% of rdg ± 3D
20V	10mV	±0.5% of rdg ± 3D
200V	100mV	±0.5% of rdg ± 3D
1000V	1V	±0.8% of rdg ± 3D

OVERLOAD PROTECTION: 220V rms AC for 200mV range and 1000V DC or 750V rms for all

ranges.

AC VOLTAGE

RANGE	RESOLUTION	ACCURACY
200V	100mV	±1.2% of rdg ± 10D
750V	1V	

RESPONSE: Average responding, calibrated in rms of a sine wave.

FREQUENCY RANGE: 45Hz ~ 450Hz

OVERLOAD PROTECTION: 1000V DC or 750V rms for all ranges.

DC CURRENT

RANGE	RESOLUTION	ACCURACY
200μA	100nA	±1% of rdg ± 3D
2000μA	1μA	±1% of rdg ± 3D
20mA	10μA	±1% of rdg ± 3D
200mA	100μA	±1.5% of rdg ± 5D
10A	10mA	±2% of rdg ± 10D

OVERLOAD PROTECTION: 200mA 250V fuse (10A range unfused).

MEASURING VOLTAGE DROP: 200mV

RESISTANCE

RANGE	RESOLUTION	ACCURACY
200Ω	100mΩ	±1.0% of rdg ± 10D
2000Ω	1Ω	±1.0% of rdg ± 2D
20KΩ	10Ω	±1.0% of rdg ± 2D
200KΩ	100Ω	±1.0% of rdg ± 2D
2000KΩ	1KΩ	±1.0% of rdg ± 2D

MAXIMUM OPEN CIRCUIT VOLTAGE: 3.2V
OVERLOAD PROTECTION: 15 seconds maximum 220Vrms.

AUDIBLE CONTINUITY

RANGE	DESCRIPTION
•••	Built-in buzzer sounds if resistance is less than 30 ± 20Ω

OVERLOAD PROTECTION: 15 second maximum 220 V rms.

TEMPERATURE (K TYPE PROBE)

RANGE	RESOLUTION	ACCURACY
-20°C to 1370 °C	1°C	±3°C ± 2D (up to 150°C) ±3% of rdg (over 150°C)

OPERATING INSTRUCTIONS

WARNING

To avoid electrical shock hazard and/or damage of the instrument, do not measure voltages that might exceed 500V above earth ground.

Before the use of instrument, inspect test leads, connectors and probes for cracks, breaks, or crazes in the insulation.